

WHAT'S WRONG WITH THIS PIC?



Topside with Capt Obvious

Good on the Sailor for getting after topside corrosion, but notice he's wearing a fall arrest harness which isn't actually connected to anything. Equipment can't perform if it's not used properly. Bonus points for also noticing the removeable nylon lifelines in the foreground, one isn't connected and none of them meet PMS requirements regarding droop.