


**It takes 80,000 rivets,
30,000 washers, and 10,000
screws and bolts to help
make this aircraft fly ...
and one nut to destroy it.**



Make FOD walkdowns count.



FOD walkdown photo by PH3 Yesenia Rosas

Naval Safety Center
www.naval safety center.navy.mil

