

FLIGHT CONTROLS HITTING OPENED PANELS DUE TO SWITCHES OR COCKPIT CONTROLS NOT IN CORRECT POSITION,
PANELS THAT WEREN'T PROPERLY INSTALLED,
FASTENERS THAT WERE NOT PROPERLY INSTALLED,
AS WELL AS ENGINES INGESTING FOD
HAVE BEEN A LEADING CAUSE OF HORNET AND GROWLER CLASS B AND C MISHAPS.