

FORKLIFT *OPS*

DID YOU KNOW?

FROM 2014 TO 2020, 83 PERCENT OF SHIPBOARD FORKLIFT MISHAPS OCCURED DUE TO THE FOLLOWING FACTORS:



21%
DURING
FORKLIFT TIME
ADJUSTMENT

21%
PERFORMING
FORKLIFT
MAINTENANCE
(MX)

39%
SAFETY
OBSERVER
FAILURE

18%
FORKLIFT
CREW ERROR

- ENSURE TRAINING IS COMPLETE AND CURRENT.
- MAINTAIN SITUATIONAL AWARENESS.
- FOLLOW MAINTENANCE PROCEDURES AND LOCAL SAFETY OBSERVER GUIDANCE.
- MAINTAIN SIGHTLINES AND CONTROL OF OPERATIONS.
- BE READY TO ACT AND STOP UNSAFE FORKLIFT OPERATIONS.

NAVALSAFETYCENTER.NAVY.MIL

