



NAVAL SAFETY COMMAND

**SAFETY AWARENESS DISPATCHES and
SANTIZED SAFETY INVESTIGATION REPORTS**



SA and SSIR Summary List: CY 2023 – CY 2025

Safety Awareness Dispatches

SA 23-01 Winter Driving Mishaps
SA 23-02 Afloat Electrical Mishaps
SA 23-03 Traumatic Brain Injuries
SA 23-04 Aviation Maintenance Mishaps
SA 23-05 PPE Related Mishaps
SA 23-06 Inattention
SA 23-07 Hazardous Material Mishaps
SA 23-08 Why You Should Wear Your Seatbelt
SA 23-09 Hawthorne Mortar Mishap
SA 23-10 The Importance of Training
SA 23-11 The "Summery" of Mishaps
SA 23-12 Lithium-Ion Battery Fires
SA 23-13 Rip Currents
SA 23-14 Off-Duty Firearms Mishaps (Edition VIII)
SA 23-15 Motorcycle Mishaps III
SA 23-16 E-Scooter Mishaps V
SA 23-17 What is the SMS And Why Should I Care?
SA 23-18 Bladed Tool Mishaps
SA 23-19 Amphibious Combat Vehicle Mishaps
SA 23-20 Heat Stress Mishaps
SA 23-21 Team Sports Injuries
SA 23-22 All-Terrain Vehicle Mishaps
SA 23-23 What is Risk Registry and Why Do You Need One?
SA 23-24 Physical Fitness Injuries II
SA 23-25 M-18 Service Pistol Mishaps
SA 23-26 Tactical Vehicle Mishaps
SA 23-27 Physical Training Injuries II
SA 23-28 Motorcycle Fatalities
SA 23-29 Fall-ing Down
SA 23-30 Gun and Bow Mishaps (Hunting Edition)
SA 23-31 Shipboard Ladder Mishaps IV
SA 23-32 USS SATURN Shipyard Fire
SA 23-33 Casualty Evacuation Failures
SA 23-34 Holiday Hazards
SA 23-35 Communication Breakdowns
SA 23-36 Winter Driving II
SA 24-01 Winter Sports V
SA 24-02 Weight Handling Mishaps
SA 24-03 The Office Mishaps
SA 24-04 Knife Mishaps III
SA 24-05 Gym Mishaps
SA 24-06 Why Don't We Follow the Procedures
SA 24-07 Motorcycle Mishaps IV
SA 24-08 Towed Array Mishaps
SA 24-09 Backyard Blunders
SA 24-10 Off-Duty Firearms Mishaps IX
SA 24-11 E-Scooter Mishaps VI
SA 24-12 Pedestrian Mishaps II
SA 24-13 Water Related Mishaps
SA 24-14 A Tale of Two Sonar Domes
SA 24-15 The Consequences of Not Speaking Up
SA 24-16 Heat Stress Mishaps
SA 24-17 Summer Driving Mishaps
SA 24-18 Failed Carrier Arresting Wire; A Root Cause Analysis
SA 24-19 Aviation Electrical Shocks
SA 24-20 The 50.5 Critical Days of Summer
SA 24-21 On-Duty Negligent Discharges
SA 24-22 Pierside Heavy-Weather Mishaps
SA 24-23 Random Acts of Senselessness Summer Edition
SA 24-24 Ship Grounding During Inbound Transit
SA 24-25 M320 Grenade Launcher Mishaps
SA 24-26 Shipboard Ladder Mishaps V
SA 24-27 If You Ride a Motorcycle Read This
SA 24-28 On-Duty Boat Mishaps
SA 24-29 101 Critical Days of Summer Wrap Up
SA 24-30 Live Fire and Maneuver Mishaps
SA 24-31 Autumn Outdoor Mishaps
SA 24-32 Outdoor Fires
SA 24-33 Underway Replenishment Mishaps
SA 24-34 Off-Duty Firearms X
SA 24-35 Winter Sports VI
SA 24-36 Winter Driving III
SA 25-01 Aircraft Towing and Towing Equipment Mishaps
SA 25-02 Explosive Demolition and Breaching Mishaps
SA 25-03 Motorcycle Mishaps V
SA 25-04 Latent Failures
SA 25-05 Knife Mishaps IV
SA 25-06 High-Risk Training
SA 25-07 The Dangers of Doors and Hatches
SA 25-08 E-Scooter Mishaps (Episode VII)
SA 25-09 Underway Replenishment Emergency Breakaway
SA 25-10 Bicycle Mishaps II
SA 25-11 Eye Injuries

SA and SSIR Summary List: CY 2023 – CY 2025

SA 25-12 Heat-Related Injuries
SA 25-13 Off-Duty Falls From Height
SA 25-14 Shipboard Ladder Mishaps VI
SA 25-15 Shipboard Fires
SA 25-16 Swim-Related Mishaps
SA 25-17 Risk Registry Explained
SA 25-18 All-Terrain Vehicle Mishaps
SA 25-19 Things Falling Off Aircraft (TFOA)
SA 25-20 Drunk Driving Mishaps
SA 25-21 Machine Gun Ammo Cook Offs
SA 25-22 Lithium-Ion Battery Mishaps II
SA 25-23 Pedestrian Safety
SA 25-24 Pre-Existing Medical Conditions
SA 25-25 Ladder Falls
SA 25-26 101 Critical Days of Summer Wrap Up-2025
SA 25-27 Tactical Vehicle Mishaps II
SA 25-28 Stair-Related Mishaps
SA 25-29 Outdoor Fire Fails
SA 25-30 Vertical Replenishment Mishaps
SA 25-31 Motorcycle Mishaps
SA 25-32 Bridge Resource Management
SA 25-33 Fatigue-Related Mishaps

Sanitized Safety Investigation Reports

SSIR 23-01 Artillery Misfire Mishap
SSIR 23-02 Man Overboard
SSIR 23-03 Helicopter Pilot Spatial Disorientation
SSIR 23-04 Reconnaissance Training Drowning
SSIR 23-05 Helicopter Unintentional Yaw On Deck
SSIR 23-06 On-Duty Hammock Fatality
SSIR 23-07 Night Live Fire and Maneuver Mishap
SSIR 23-08 Ship Allision With Buoy
SSIR 23-09 Parachute Landing Fatality
SSIR 23-10 Ship's Boat Hoisting Mishap
SSIR 23-11 Aircrew Shut Down Wrong Engine
SSIR 23-12 Combatant Craft Grounding
SSIR 24-01 Controlled Flight Into Terrain
SSIR 24-02 Unexploded Ordnance Clearing Mishap
SSIR 24-03 Loss of Unmanned Underwater Vehicle
SSIR 24-04 Underway Replenishment Near Miss
SSIR 24-05 Ship Grounding While Shifting Berths
SSIR-24-06 Tactical Vehicle Rollover
SSIR 24-07 Heat Injuries During Training Hike
SSIR 24-08 Parachute Fatality
SSIR 24-09 Ship's Main Reduction Gear Casualty
SSIR 24-10 Unnecessary Helicopter Autorotation
Mishap

SSIR 24-11 Emergency Egress System Explodes During Maintenance
SSIR 25-01 Combat Rubber Reconnaissance Craft Mishap
SSIR 25-02 Unintended Parachute Water Landing
SSIR 25-03 Night Live Fire and Maneuver Mishap

Safety Awareness Division POCs

Safety Awareness Specialist
(757) 444-3520 ext. 7269 / DSN 564-3520

Safety Awareness Specialist
(757) 444-3520 ext. 7126 / DSN 564-3520

Group email:
navsafecom_code04_pao@us.navy.mil

Library of SAs and SSIRs

A. NAVSAFECOM Public Website

<https://navalsafetycommand.navy.mil/>

1. On the home page in the "Media" Tab, select "Safety Awareness"

Note: This page contains our [publicly releasable](#) Safety Awareness (SA) dispatches and lessons learned only. It also has a link to the CAC-enabled website (below) which has the full library of SSIRs and SAs (formerly LLs).

B. NAVSAFECOM CAC-enabled Website

<https://intelshare.intelink.gov/sites/nsc/>

New Users must request access to the website.

1. Click the "Safety Awareness Products" icon on the main page (*right side; look for the SA products sign*).

2. Under "Safety Awareness Communities", click your desired community folder.

***Note:** This page has our **full library** of SSIRs and SAs (formerly LLs).*

And remember, "Let's be careful out there."