

WAIT!

NavalSafetyCommand.Navy.Mil

Did you do a thorough panel and switch check?

Maintenance turns and applying external hydraulics to aircraft without switches in correct positions and ensuring movable control surfaces are clear have been among the top three aviation ground mishaps for the Hornet and Growler communities for the past decade.

