

# WHAT'S WRONG WITH THIS PIC?



**Well hello Capt Obvious,**

**This is an area onboard a ship that requires lifelines to prevent personnel from falling overboard. Although available, 2 of the 3 lifelines are not properly connected to prevent individuals from falling over the side of the ship. One is simply NOT enough to prevent an unplanned trip overboard. It appears someone left the lines ope for a BAD outcome.**

**It is obvious why this is an unwelcome sight.**