

**Did you inspect canopy sills and dorsal deck for foreign objects (FOD) before closing the canopy?**

Over the last seven years, canopy and canopy sill plate damage have ranked in the top five F/A-18 and E/A-18 Class C mishaps due to damage from shutting them on tools, hoses, couplings, helmets and hardware.



**STOP!**



NavalSafetyCommand.Navy.Mil